



Bracket set 300 311 2604/HD
 Bushing set 300 311 2919/HD

Reference No.
 31 12 6 783 376

Bracket set with bushings and screws to fit BMW E46, Z4



as OE

Problem

- Use of soft bushing for best possible comfort
- High dynamic strain causes leakage of the hydro-liquid

Effect

- Disturbing torsional vibration from the front axle; reduced durability
- Vibration in the steering
- Reduced driving comfort

Solution

Replacing the hydro mount with a full rubber mount

Advantage

- Dangerous vibrations are reduced
- Significant longer lifetime with more driving comfort
- Bushings can be replaced separately (unlike OE)

